Boot Options & OS Versions

Mobile Products – Current and Legacy

◇DATALOGIC
AUTOMATIC DATA CAPTURE

Product CE OS WM OS	WARM BOOT	COLD BOOT	CLEAN BOOT
ELF CE60=1.90 WM65=1.90	Yellow + Blue + Red Phone	Hold down Scan then Reset under battery	Cold / Red Phone + 0
LYNX WM65=1.86	Yellow + Blue + Red Phone	Reset under battery	Warm / Red Phone + 0
FALCON X3 CE60=1.90 WM65=1.90	Yellow + Blue + ESC	Hold down Scan then Reset under battery	Cold / ESC + 0
FALCON X3 Plus CE60=1.92 WM65=1.92	Yellow + Blue + ESC	Hold down Scan then Reset under battery	Cold / ESC + 0
MEMOR CE50 = 4.40 WM61 = 4.40	ESC + Power	ESC + Toggle + Power	Cold / ESC + 0
MEMOR X3 WinCore and Pro: 1.00.23	ESC + Power	ESC + Enter + Power	Cold / ESC + 0
SKORPIO CE50=3.30 WM61=3.30	Yellow + Blue + Scan	Yellow + Dn Arrow + Blue + Scan	Cold / ESC + 0
SKORPIO X3 CE60=1.90 WM65=1.90	Yellow + Blue + ESC	Hold down Scan then Reset under battery	Cold / ESC + 0
KYMAN CE50=3.30 WM61=3.30	F1 + Scan + Power	F1 + F2 + Scan + Power	Cold / ESC + 0

Product CE OS / WM OS	WARM BOOT	COLD BOOT	CLEAN BOOT
RHINO CE6.0 = 1.2.2	\Windows directory Run Reboot Command Or Remove upper left panel and press the push button	\Windows directory Run Cold Reboot Command	Warm or Cold Boot then press and hold UP + DOWN keys until the touch calibration screen appears
JOYA X1 / X2 / A	Press the "+" (plus) and "-" (minus) keys simultaneously for 5 seconds	Lightly press a metallic clip inside the circle hole on the back.	Cold boot and immediately press and hold "=" and "-". Press "e" when pop up box appears
FALCON 4400 26 Key CE50=3.16 WM5=3.19	FN + ALPHA + BKSP	Paper Clip + Power	CE: Delete all files in 'FlashFX Disk' / Cold Boot WM: Warm Boot / ESC + 0
FALCON 4400 48 Key CE50=3.16 WM5=3.19	CTRL + ALT + BKSP	Paper Clip + Power	CE = Delete all files in 'FlashFX Disk' / coldboot WM: Warm Boot / ESC + 0
FALCON 4400 52 Key CE50=3.16 WM5=3.19	ALT + FN + F1	Paper Clip + Power	CE = Delete all files in 'FlashFX Disk' / Cold Boot WM: Warm Boot / ESC + 0

Product CE OS WM OS	WARM BOOT	COLD BOOT	CLEAN BOOT	SAFE BOOT
FALCON 4400 52NU Key CE50=3.16 WM5=3.19	CTRL + ALT + DEL	Paper Clip + Power	CE = Delete all files in 'FlashFX Disk' / Cold Boot WM: Warm Boot / ESC + 0	**FALCON 4400** 52NU Key CE50=3.16 WM5=3.19
FALCON 31X	CTL + ALT + DEL	Short pins under card OR ALT + FN2 +PWR	Type Format [ENTER] at C prompt	Warm or Cold boot + (ESC + DEL)
FALCON 32X	CTL + ALT + DEL	Short pins under card	Type Format [ENTER] at C prompt	Warm or Cold boot + (ESC + DEL)
FALCON 33X 25 Key	LAMP + FN + BACKSPACE	Paperclip	Type Format [ENTER] at C prompt	Paperclip – when "Waiting…" appears press ESC + TAB
FALCON 33X 38 Key	CTL + ALT + DEL	Paperclip	Type Format [ENTER] at C prompt	Paperclip – when "Waiting…" appears press ESC + SPACE
PEGASO CE50=3.14 WM60=3.16	AZ + ESC + 3	Reset under battery	Warm / ESC + 0	Cold boot, then hold ESC + 5

DATALOGIC
AUTOMATIC DATA CAPTURE

Product CE OS WM OS	WARM BOOT	COLD BOOT	CLEAN BOOT	SAFE BOOT
FALCON 4220 CE42=4.10	Reset Button	Reset Button + F2	FORMAT/ PARTITION OR Delete Reg1 and Reg 2 – Cold Boot	Cold boot then hold F1 to Desktop
FALCON 34X 25 Key	LAMP + FN + BACKSPACE	Paperclip	Type Format [ENTER] at C prompt	Paperclip – when "Waiting…" appears press ESC + TAB
FALCON 34X 38 Key	CTL + ALT + DEL	Paperclip	Type Format [ENTER] at C prompt	Paperclip – when "Waiting…" appears press ESC + SPACE
FALCON 34X 48 Key	CTL + ALT + DEL	Paperclip	Type Format [ENTER] at C prompt	Paperclip – when "Waiting…" appears press ESC + SPACE
JET	FN1 + SCAN + PWR	F1 + F2 + SCAN + PWR	COLD BOOT, press ESC + 0	-
PT2000 4.73	-	-	Remove battery Press Alpha + Enter Insert battery	-
PT40 5.70	Reset barcode in the PRG manual	-	Remove battery Press CLR + ENT Insert battery	-

www.adc.datalogic.com

Thank you!

◆DATALOGIC
AUTOMATIC DATA CAPTURE