

CN70|CN70e

Scan Handle Instructions

扫描手柄说明

描握把説明

Poignée de lecture - Instructions

Anleitung für Scan-Griff

スキャン・ハンドルの取り扱い

핸들 스캔 지침

Instruções do punho do digitalizador

Инструкции по обращению с ручкой сканера

Instrucciones para el mango del escáner

คำแนะนำเกี่ยวกับที่จับสำหรับสแกน

To attach the handle

连接手柄

附加握把

Pour attacher la poignée

Anbringen des Griffs

ハンドルを取り付けるには




핸들을 연결하려면

Acoplar o punho

Чтобы прикрепить ручку

Para instalar el mango

การติดตั้งที่จับ



To remove the handle

取下手柄

取下握把

Pour retirer la poignée

Entfernen des Griffs

ハンドルを取り外すには




핸들을 제거하려면

Retirar o punho

Чтобы снять ручку

Para retirar el mango

การถอดที่จับ



Worldwide Headquarters
6001 36th Avenue West
Everett, Washington 98203
U.S.A.

tel 425.348.2600

fax 425.355.9551

www.intermec.com

© 2010 Intermec Technologies
Corporation. All rights reserved.



CN70 and CN70e Scan Handle Instructions



P/N 943-260-001