
MOUNTING BRACKET INSTALLATION GUIDE



Zebra reserves the right to make changes to any product to improve reliability, function, or design. Zebra does not assume any product liability arising out of, or in connection with, the application or use of any product, circuit, or application described herein. No license is granted, either expressly or by implication, estoppel, or otherwise under any patent right or patent, covering or relating to any combination, system, apparatus, machine, material, method, or process in which Zebra products might be used. An implied license exists only for equipment, circuits, and subsystems contained in Zebra products.




Zebra Technologies Corporation Lincolnshire, IL U.S.A. http://www.zebra.com

Zebra and the Zebra head graphic are registered trademarks of ZIH Corp. The Symbol logo is a registered trademark of Symbol Technologies, Inc., a Zebra Technologies company. © 2015 Symbol Technologies, Inc





RACK MOUNTING



- 1. Align mounting holes on the bracket with screw holes on the rack.
- 2. Secure the bracket to the rack using rack screws.








WALL MOUNTING

CAUTION:

Use mounting hardware (screws and/or anchors) appropriate for the type of wall you are mounting the bracket onto. The Wall Mount Bracket mounting slots dimensions are 5 mm (0.2 in.). Fasteners must be able to hold a minimum of 15 Kg (33 lbs.)

For proper installation consult a professional installer. Failure to install the Mounting Bracket properly can possibly result in damage to the hardware.







8. Secure the flange to the bracket using thetwo screws.

9. Repeat for the other side of the bracket.


MOUNTING THE FIVE SLOT UNIVERSAL CHARGE ONLY CRADLE




- 1. Install four screw studs into the threaded holes as shown.
- 2. Secure the screw studs using a Phillips screwdriver.



- 5. Place the power supply into the shelf under the bracket.
- 6. Plug the AC Line Cord into the power supply.
- 8. Use tie wraps to secure the cables to the bracket, as required.



MOUNTING 5 FOUR SLOT BATTERY CHARGERS




- 2. Secure the screw studs using a Phillips screwdriver.


- 3. Align the screw slots on the bottom of the crasdle with the four Screw Studs on the bracket.
- 4. Place the cradle only the studs and slide down.

- 7. Plug the DC cable into the power input of the cradle.

1. Install twenty screw studs into the threaded holes as shown.



- 3. Align the screw slots on the bottom of the chargers with the four Screw Studs on the bracket.
- 4. Place the charger onto the studs and slide down.



- 5. Place each power supply into the shelf under the bracket.
- 6. Plug an AC Line Cord into each power supply.
- 7. Plug the DC cable into the power input of each charger.
- 8. Use tie wraps to secure the cables to the bracket, as required.



